

Product/maintenance information No. 2015-1

Date: 2015-12-15
Implementing date: 2015-01-01
Approved by: Martin Johansson

Automatic De-airing

Background:

When supplying high volumes of water to our units, customer have had problems with air coming in with the inlet water and this air has been trapped in the top of the pump causing the shaft seal to break due to no water lubrication. This has been a problem especially on the 40 bar pumps.

Please, see picture on page 2.

Action:

From January 2015 all units in the 40 bar range (excl CB) has an automatic de-airing valve installed on each pump. It will not affect the price and it will be delivered as standard. Article number is clearly stated in the manual.

Picture attached!

If you have any questions, please let us know!

Lagafors Fabriks AB



Product Manager
Martin Johansson

Picture

